

BURR KING MFG. CO., INC.

1220 TAMARA LANE WARSAW MO 65355 WWW.BURRKING.COM

(660) 438-8998 + (800) 621-2748 FAX (660) 438-8991

NEWS FLASH

August 3, 2021

Safety Concerns?

<u>Upgrade your Burr King Model 482</u>

to New Style Guarding

Upgrade an older model 482 (pre August 2021) to one that incorporates the latest belt guarding and pinch point protection and get the following advantages!

- Deeper horizontal throat clearance to better address hard to reach areas
- Greater vertical throat clearance to better address odd shaped parts
- Improved contact wheel side access to better address odd shaped parts
- Improved dust management to optimize vacuum dust extraction
- Improved guard door latching
- Improved nylon belt performance that eliminates the rear spring "catch issue"
- Improved belt clearance that minimizes the "ticking" issue with nylon belts
- Improved adaptability provided by an enlarged, flattened front guard face
- Contact wheel pinch point protection even with the platen assembly removed
- Full width contact wheel guarding
- Belt path guarding that takes "broken belt", pinch point, hand insertion, and debris ejection operator protection to even safer levels!
- Belt path guard ready to accept front face scatter shield (part number 442SS)
- Stronger Backup Platen ¼" Steel

Call your local dealer or Burr King Manufacturing and request part #498

- which includes the following
- 442-2 safety guard assembly
- 403-1 contact wheel guard
- 404-1 platen assembly





Adding only the 442-2 safety guard assembly does **not** provide sufficient protection from pinch points, and other rotational hazards. The owner of the equipment is urged to purchase the complete kit for compliance.